

BREAK command

2013 GstarCAD MY /KW April 14, 2022 [CAD Commands](#) 0 1575

The **BREAK** command is used to break specified object by selected two points.

Command Access:

Ribbon : Home > Modify > Break

Ribbon : Home > Modify > Break at a point

Menu : Modify > Break

Command : BREAK


Command Prompts:

Select object:

Specify second break point of [First point]:

Function Description:

Create an interval by two specified points to break object. If the second point is outside of the select object, it will be projected to selected object. The BREAK command is usually used to create intervals for a block or text.



Relative glossary:


Second break point:

Specify the second point to break selected object.


First point:

Specify a new point to instead the first defined point. The distance between the two selected points will be deleted. If the second point is out of the select object, the second point will be instead by the nearest


point on the object. So to break one side of a straight line, an arc, or a polyline, users could specify the second break point near the side.



To break an object without deleting one part, users could specify the second point the same as the first point, or input the coordinate of the second point with @. There are many objects could be broken into two parts or removed one of them, such as straight line, arc, circle, polyline, ellipse, spline, torus and others. Taking a circle for example, it could be broken from the first point to the second point in anticlockwise direction, and turns it to an arc.



Users could also break an object at a point by the "BREAK AT POINT" tool. This command could break straight line, open polyline and arc except closed objects (such as circle).



Related tutorial video:

- [Status bar related setting](#) 00:15
- [Draw Rectangles and Polygons](#) 00:26
- [Rectang command](#) 00:26
- [Polygon command](#) 00:26
- [Arc command](#) 00:30
- [Trim command](#) 00:40
- [Extend command](#) 01:51
- [Offset command](#) 02:23
- [Stretch command](#) 03:35
- [Edit objects + grips](#) 03:55
- [Break object](#) 04:13
- [Circle command](#) 05:51
- [Draw circles](#) 05:51
- [Break command](#) 05:56
- [Join command](#) 06:32
- [Scale command](#) 06:53
- [Lengthen command](#) 07:29
- [Copy command](#) 08:20
- [Rotate command](#) 08:47
- [Move command](#) 09:07

Above video sources from [TUTORIAL - GETTING STARTED WITH GSTARCAD](#), enrol now for free.

Online URL: <https://kb.gstarcad.com.my/article/break-command-2013.html>