

# LAYERPMODE command

2177 GstarCAD MY /KW August 17, 2021 [CAD Commands](#) 0 865

The **LAYERPMODE** command is used to turn on or turn off trace mode about layer settings.

## Command Access:

Command : LAYERPMODE

## LAYERPMODE command

Enter LAYERP mode [ON/OFF] <ON>:

## Function Description:

If the LAYERP mode is turned on, layer changes will be traced. If the LAYERP mode is turned off, layer changes will not be traced.

Online URL: <https://kb.gstarcad.com.my/article/layerpmode-command-2177.html>