## Draw Axonometric Line

1051 GstarCAD Malaysia June 30, 2021 Unique function 0 3799

Using this function can easily draw an axonometric drawing

**Menu** : Express > GstarCAD Tools > Draw Axonometric Line **Command Entry** : SALPL

## **Operation steps:**

1.Start the command.

2.Input the line width value.

3. The command line will prompt as below, input corresponding options, you can use it to switch between 0 degree and 45 degree and you can also input any angle value.

4	∎odel	Lay	out1	Layout2					
Counterclo Command: Wait for e			(A) /	clockwise	coarse	(D) /	counterclo	ckwise	Fir
Command: S Please ent Starting p	er a dr	awing	line w	vidth: <o></o>					
× .		input :	angle(	I)/O degre	e(.)/ 45	degro	ee(/)/ <next< td=""><td>point)</td><td>&gt;:</td></next<>	point)	>:

4.Enter to finish the command.

Online URL: <u>https://kb.gstarcad.com.my/article/draw-axonometric-line-1051.html</u>