Overview of Layers

2473 GstarCAD MY /KW April 15, 2022 Workflow 0 991

As the main organizational tool for drawings, \underline{LAYER} can be used to group information by function and to enforce $\underline{LINETYPE}$, \underline{COLOR} and other standards.

The following settings can be controlled: the default color, default linetype and lineweight (<u>LWEIGHT</u>), visibility and brightness, modify and display objects with different layer properties in individual layout viewports.

You start each new drawing with a layer named 0. This layer 0 cannot be deleted or renamed for the following reasons:

- Every drawing has at least one layer
- It is a special layer that relates to controlling colors in blocks

Related tutorial video:

- Overview of layer 00:20
- Line command 00:37
- <u>Draw Lines</u> 00:37
- Properties command 00:54
- Properties close command 00:54
- LAYISO command 01:10
- LAYUNISO command 01:16
- LAYER command 01:20
- Change layer settings and layer properties 01:21
- LAYMCUR command 02:04
- LAYDEL command 02:48

Above video sources from <u>TUTORIAL</u> - <u>GETTING STARTED WITH GSTARCAD</u>, enrol now for free.

Online URL: https://kb.gstarcad.com.my/article/overview-of-layers-2473.html